

Well House

ML-13

ML-14

Storage

10 Active water leaks

WL-12

WL-11

Break Room

Maintenance

WL-10

Coat Room RR RR WS-9 Utility Storage

6 water stains

WS-8

M-8 Engineering

RR Maint Engineering WS-5

WS-4

M-1

Legend

- M-1 Observed Mold
- WL-1 Active Water Leak
- WS-2 Water Stain (no observed mold/must)

CONTOUR ENGINEERING

A Universal Engineering Sciences Company

Sampling Locations for
Former Whitpath Fab Tech
118 Industrial Blvd.
Blue Ridge, Georgia

Date 3/28/21
Prepared By: KLM
Fluorescent
Sheet No:
Page No: 4